

**C=0 SAMPLING PLANS
INDEX VALUES
(ASSOCIATED AQLS)**

	.010	.015	.025	.040	.065	.10	.15	.25	.40	.65	1.0	1.5	2.5	4.0	6.5	10.0
LOT SIZE	SAMPLE SIZE															
2 to 8	*	*	*	*	*	*	*	*	*	*	*	*	5	3	2	2
9 to 15	*	*	*	*	*	*	*	*	*	*	13	8	5	3	2	2
16 to 25	*	*	*	*	*	*	*	*	*	20	13	8	5	3	3	2
26 to 50	*	*	*	*	*	*	*	*	32	20	13	8	5	5	5	3
51 to 90	*	*	*	*	*	*	80	50	32	20	13	8	7	6	5	4
91 to 150	*	*	*	*	*	125	80	50	32	20	13	12	11	7	6	5
151 to 280	*	*	*	*	200	125	80	50	32	20	20	19	13	10	7	6
281 to 500	*	*	*	315	200	125	80	50	48	47	29	21	16	11	9	7
501 to 1200	*	800	500	315	200	125	80	75	73	47	34	27	19	15	11	8
1201 to 3200	1250	800	500	315	200	125	120	116	73	53	42	35	23	18	13	9
3201 to 10,000	1250	800	500	315	200	192	189	116	86	68	50	38	29	22	15	9
10,001 to 35,000	1250	800	500	315	300	294	189	135	108	77	60	46	35	29	15	9
35,001 to 150,000	1250	800	500	490	476	294	218	170	123	96	74	56	40	29	15	9
150,000 to 500,000	1250	800	750	715	476	345	270	200	156	119	90	64	40	29	15	9
500,001 and over	1250	1200	1112	715	556	435	303	244	189	143	102	64	40	29	15	9



*Indicates entire lot must be inspected
NOTE: The Acceptance Number in all cases is ZERO